TECTON
Construction Management, Inc.

WEST LAFAYETTE CITY HALL INSPECTION REPORT

2014

Basement Exterior Wall Inspection Locations

Sketch SK-5