Top board on side wall that supports the rafters is rotten

the end of rafter is rotten.

Back of the garage

Rotten corner of garage

East side of garage

Property was purchased September 14, 2015!

Front of garage

Another place the top board on side wall that supports the rafters is rotten.

Another end of rafter that is rotten.

Board that are under the shingles on the roof

Top board on the side wall that supports the rafters is rotten.